


**CONNECTION OF HANDHELD INTERROGATOR
DIRECTLY TO WIRING ON OPTIMA PLUS OR EXCEL
WITHOUT THE USE OF THE RECOMMENDED
SHC PROTECTION DEVICE, P/N 04230-A-1025**

**ENSURE THAT AREA IS FREE OF
FLAMMABLE GASSES AND VAPORS**

Note position of alignment tabs
on handheld interrogator connector



* Ensure interrogator is set to proper detector